



To avoid lamellar tearing, the components must be heated prior to welding - see table 3.2 of EN 1993-1-10 ($\geq 100^\circ\text{C}$)

Drawing to be read in conjunction with workshop assembly drawings